

Revised 03-10-2021	State	MN	Contractor	MN Metro	CMS#	21075862
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>						
Company	Exchange Name	MPGVMNXA			Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance		
Customer Name	will marmorine			Phone#	(763) 315-3615	
Address	11310 81st way n			One Call Ticket#		
City & Zip	maple grove					
Location/Directions	ll					
Description of Work or Special Instructions	plow fiber drop 65ft with 18ft driveway bore					
Held Order	Y	N	Permit:	Y	N	Bore:
Tech Name and Tech #	pnathe			Employee Contact#	6127159213	
Sketch	Material/Labor Units			Footage/Quantity	Comments	
(Include Cntr Line & Pedestal)	Description	Notes				
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt				
	SEB3-22T	BSW-3 & hand dig plcmt				
Ped#	9999	SEPCUTOVER		1		
Parish/County	BM83	BSW guard at house		1		
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used	
Township:	BM61(1.25)SEB	BSW Bore footage		18		
Section	SEBO PER FT LBR	Fiber & plow plcmt				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		65		
	SEB6-22	BSW-6 & plow plcmt				
	BM2(5/8)(8)	Ground Rod				
	SEBO-COIL	Fiber Coil			Coil excess on Fiber drop add 1 unit	
	Permit	Permit		1	Any placement within the ROW requires a permit	
Nearest cross st.	forestview			Plat Page	Map#	

  

driveway bore 18 ft
fiber drop 65ft

  

Originated By:	pnathe	Date:	5/19/21	Completed By:	_____	Date:	_____
Authorized By: (SRO)	_____	Date:	_____	Inspected By:	_____	Date:	_____
Authorized By: (MRO)	_____	Date:	_____		_____		_____

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker