

Revised 03-10-2021	State MN	Contractor MN Metro	CMS#	21081634 - HELD
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>				
Company	Exchange Name OSSEMNXO	Service Order# T100289626		
Work Activity Fiber-Buried	Capital Y	Maintenance N		
Customer Name PRAVEEN KISTAREDDYGARI	Phone# (763) 425-0514			
Address 8111 COTTONWOOD LN N	One Call Ticket#			
City & Zip MAPLE GROVE, MN, 55369				
Location/Directions gps				
Description of Work or Special Instructions see sketch				

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	
Tech Name and Tech #	AA10109			Employee Contact#	7632288645		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments			
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	see sketch	SEPCUTOVER					
Parish/County	BM83	BSW guard at house	1				
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used		
Township:	BM61(1.25)SEB	BSW Bore footage	70				
Section	SEBO PER FT LBR	Fiber & plow plcmt	88				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt					
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	SEBO-COIL	Fiber Coil			Coil excess on Fiber drop add 1 unit		
	Permit	Permit	1		Any placement within the ROW requires a permit		
Nearest cross st.	see sketch			Plat Page	Map#		



Originated By:	AA10109	Date:	5/28/21	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	