


| | | | | | | |
|---|---------------------------|----------|------------|------------------|----------------|-----------------|
| Revised 03-10-2021 | State | MN | Contractor | MN Metro | CMS# | 21114653 - HELD |
| CenturyLink BSW Order/Maintenance Work Authorization | | | | | | |
| Company | Exchange Name | OSSEMNXO | | | Service Order# | |
| Work Activity | Fiber-Buried | Capital | Y | Maintenance | N | |
| Customer Name | ADAM NEMITZ | | | Phone# | 763-425-0551 | |
| Address | 10700 LANCASTER LN N | | | One Call Ticket# | | |
| City & Zip | MAPLE GROVE, MN | | | | | |
| Location/Directions | gps | | | | | |
| Description of Work or Special Instructions | see sketch, QUANTUM FIBER | | | | | |

| Held Order | Y | Permit: | Y | Bore: | Y | CBR# | 612-240-8502 |
|--|----------------------|------------------------|------------------|--|------------|------|--------------|
| Tech Name and Tech # | AA10109 | | | Employee Contact# | 7632288645 | | |
| Sketch (Include Cntr Line & Pedestal) | Material/Labor Units | | Footage/Quantity | Comments | | | |
| | Description | Notes | | | | | |
| Cntr Line foot | SEB3-22 | BSW-3 & plow plcmt | | | | | |
| | SEB3-22T | BSW-3 & hand dig plcmt | | | | | |
| Ped# | see sketch | SEPCUTOVER | 1 | | | | |
| Parish/County | BM83 | BSW guard at house | 1 | | | | |
| | XXSEB-GL | Remove temp drop | | Footage when temp can't be re-used | | | |
| Township: | BM61(1.25)SEB | BSW Bore footage | 180 | | | | |
| Section | SEBO PER FT LBR | Fiber & plow plcmt | 256 | | | | |
| Range | SEBO PER FT LBR T | Fiber & hand dig plcmt | | | | | |
| | SEB6-22 | BSW-6 & plow plcmt | | | | | |
| | BM2(5/8)(8) | Ground Rod | | | | | |
| | SEBO-COIL | Fiber Coil | 1 | Coil excess on Fiber drop add 1 unit | | | |
| | Permit | Permit | 1 | Any placement within the ROW requires a permit | | | |
| Nearest cross st. | see sketch | | Plat Page | Map# | | | |



| | | | | | | | |
|----------------------|---------|-------|---------|---------------|--|-------|--|
| Originated By: | AA10109 | Date: | 7/27/21 | Completed By: | | Date: | |
| Authorized By: (SRO) | | Date: | | Inspected By: | | Date: | |
| Authorized By: (MRO) | | Date: | | | | | |

| | | | |
|---|--|---|--|
| 1. Distance of the bury in Right-of-Way | | 3. Distance to the nearest intersection | |
| 2. Distance from the terminal to the centerline | | 4. Nearest State Hwy mile marker | |