

Revised 03-10-2021	State	MN	Contractor	MN Metro	CMS#	21127328 - HELD	
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>							
Company	Exchange Name	MPGVMNXA			Service Order#	SA-86020	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N		
Customer Name					Phone#		
Address	17294 66TH PL N				One Call Ticket#		
City & Zip	MAPLE GROVE 55311						
Location/Directions							
Description of Work or Special Instructions	QF BURY TO REAR OF HOUSE						
Held Order	Y	Permit:	Y	Bore:	Y	CBR# 6122985389	
Tech Name and Tech #	DEX KOEPP			Employee Contact#	6513025304		
Sketch <small>(Include Cntr Line &amp; Pedestal)</small>	Material/Labor Units			Footage/Quantity	Comments		
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	SEPCUTOVER	CUTOVER BSW					
Parish/County	BM83	BSW guard at house		1			
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used		
Township:	BM61(1.25)SEB	BSW Bore footage		250			
Section	SEBO PER FT LBR	Fiber & plow plcmt					
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		355			
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	SEBO-COIL	Fiber Coil		1	Coil excess on Fiber drop add 1 unit		
	Permit	Permit			Any placement within the ROW requires a permit		
Nearest cross st.				Plat Page	Map#		
Originated By:	DEX KOEPP	Date:	8/18/21	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					
Email sketch to:							
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					