


Revised 03-10-2021	State	MN	Contractor	MN Metro	CMS#	21128746 - HELD
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>						
Company	Exchange Name	OSSEMNXO			Service Order#	76850
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N	
Customer Name	MOHAMED KARIM			Phone#		
Address	6928 XANTHUS LN N			One Call Ticket#		
City & Zip	MAPLE GROVE, MN					
Location/Directions	gps					
Description of Work or Special Instructions	see sketch					

Held Order	N	Permit:	Y	Bore:	Y	CBR#	6123853723
Tech Name and Tech #	AA10109			Employee Contact#	7632288645		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments		
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	see sketch	SEPCUTOVER	CUTOVER BSW	1			
Parish/County	BM83	BSW guard at house		1			
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used		
Township:	BM61(1.25)SEB	BSW Bore footage		140			
Section	SEBO PER FT LBR	Fiber & plow plcmt		250			
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt					
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	SEBO-COIL	Fiber Coil		1	Coil excess on Fiber drop add 1 unit		
	Permit	Permit		1	Any placement within the ROW requires a permit		
Nearest cross st.	see sketch			Plat Page	Map#		



Originated By:	AA10109	Date:	8/19/21	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	