

Revised 03-10-2021	State	MN	Contractor	MN Metro	CMS#	21135383-HELD
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>						
Company	Exchange Name	OSSEMNXO			Service Order#	52259
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N	
Customer Name	PATRICK MICHALSKI			Phone#		
Address	12270 86TH AVE N			One Call Ticket#		
City & Zip	MAPLE GROVE, MN					
Location/Directions	gps					
Description of Work or Special Instructions	see sketch					

Held Order	Y	N	Permit:	Y	N	Bore:	Y	N	CBR#	6124321754
Tech Name and Tech #	AA10109			Employee Contact#	7632288645					
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments						
	Description	Notes								
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt								
	SEB3-22T	BSW-3 & hand dig plcmt								
Ped#	see sketch	SEPCUTOVER	1							
Parish/County	BM83	BSW guard at house								
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used						
Township:	BM61(1.25)SEB	BSW Bore footage	155							
Section	SEBO PER FT LBR	Fiber & plow plcmt	220							
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt								
	SEB6-22	BSW-6 & plow plcmt								
	BM2(5/8)(8)	Ground Rod								
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit						
	Permit	Permit	1	Any placement within the ROW requires a permit						
Nearest cross st.	see sketch		Plat Page	Map#						



Originated By:	AA10109	Date:	9/1/21	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					
Email sketch to:							
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			