


MN Metro

CMS 21047727 - HELD

Revised 2-10-2020	State MN	Contract#
CenturyLink BSW Order/Maintenance Work Authorization		
Company	Exchange Name	Service Order#
Work Activity SA-162348	Capital	Maintenance <input checked="" type="checkbox"/>
Customer Name Haci Farm Vadavely	Phone#	1000288619
Address 11239 82nd Pl N	One Call Ticket#	
City & Zip Maple Grove, 55311		
Location/Directions		
Description of Work or Special Instructions Bore 100 feet under 2 driveways then bury the remaining 45 feet to west side of house		
Field Order	Permit: <input checked="" type="checkbox"/> N	Bore: <input checked="" type="checkbox"/> N
Tech Name and Tech # Corey Watson - UltraVue AD00432	Employee Contact#	612-705-6946
Sketch	Material/Labor Units	Footage/Quantity
Include Only: Core & Pedestal	Description	Notes
Unit Line Code	SE83-22	BSW-3 & plow picmt
	SE83-22T	BSW-3 & hand dig picmt
Field	SEPCUTOVER	CUTOVER BSW
Parish/County	SO83	BSW guard at house
	XXSE8-01	Remove temp drop
Township	BM611.25/SE8	BSW Bore footage
Section	SE80 PER FT LBR	Fiber & plow picmt
Range	SE80 PER FT LBR Y	Fiber & hand dig picmt
	SE86-22	BSW-6 & plow picmt
	BM2(5/8)(8)	Ground Rig
	Trip Charge	Trip Charge
	Permit	Permit
Related CROSS ST.	83rd Ave N	Post Page



Originated By: _____	Date: _____	Completed By: _____	Date: _____
Authorized By: (SRO) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (MRO) _____	Date: _____		

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the cartline	4. Nearest State they mile marker