


CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name OSSEMNXO	Service Order#	
Work Activity	Fiber-Buried	Capital	Y
Customer Name		Phone#	(100) 034-8734
Address	9797 101st PI N	One Call Ticket#	
City & Zip	Maple Grove MN		
Location/Directions	GPS		
Description of Work or Special Instructions	Plow 80 ft of 3 pair drop from ped to pole.		

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	
Tech Name and Tech #	Don Evans			Employee Contact#	6124303133		

Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	A0A0A	SEPCUTOVER		
		CUTOVER BSW		
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	150	
Section	SEBO PER FT LBR	Fiber & plow plcmt	190	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	Brooklyn Blvd		Plat Page	Map#



Originated By: Don Evans	Date: 3/24/22	Completed By: _____	Date: _____
Authorized By: (SRO) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (MRO) _____	Date: _____	_____	_____

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker	