


**CenturyLink BSW Order/Maintenance Work Authorization**

Company	Exchange Name	MPGVMNXA	Service Order#
Work Activity	Fiber-Buried	Capital	Y
Customer Name	Alex willing	Phone#	(150) 001-3503
Address	10703 pilgrim ln n	One Call Ticket#	
City & Zip	maple grove 55369		
Location/Directions	lancaster		
Description of Work or Special Instructions	bore neighboring yard and hand dig to the back of the house were the flag is under the deck riser tube , this order on hold till drop is placed		

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	76382323414
Tech Name and Tech #	cory cook		Employee Contact#	7632287153			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	f	SEPCUTOVER		
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	118	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	240	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	107th place		Plat Page	Map#



Originated By:	Date: 6/30/22	Completed By:	Date:
Authorized By: (SRO)	Date:	Inspected By:	Date:
Authorized By: (MRO)	Date:		

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker