



Local
CMS#

CMS#

Permit 17019995

CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Capital x Maintenance _____
 Customer Name KIMBERLY MEISTEN Phone# 763-391-9400
 Address 11846 85TH PL N One Call Ticket# _____
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions Plow multiple town homes. Sprinklers. This is Fiber. Bore total: 175' Fiber total: 1050' feet.

DOR/TOG Yes ___ No x Permit: Yes ___ No x Bore: Yes x No ___ CBR# N/A
 Employee Name Kris Townsend Employee Contact# 612-715-9060


Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____

Damaged facility # _____

SKETCH

Tax Code _____



Originated By: Townsend Date: 1/24/17 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____