


CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	MPGVMNXA	Service Order#	A00090907	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	GRANT CHELSTROM		Phone#	(100) 034-8734	
Address	9797 101ST PL N		One Call Ticket#		
City & Zip	MAPLE GROVE 55369				
Location/Directions					
Description of Work or Special Instructions	QF. BURY PED TO POWER METER. HARDENED END AT HOUSE,				

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	6127519613
Tech Name and Tech #	DEX KOEPP		Employee Contact#	6513025304			
Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units		Footage/Quantity	Comments			
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	SEPCUTOVER	CUTOVER BSW					
Parish/County	BM83	BSW guard at house	1				
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used			
Township:	BM61(1.25)SEB	BSW Bore footage	200				
Section	SEBO PER FT LBR	Fiber & plow plcmt	250				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt					
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit			
	Permit	Permit	1	Any placement within the ROW requires a permit			
Nearest cross st.			Plat Page		Map#		



Originated By:	DEX KOEPP	Date:	3/22/22	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	