


CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	MPGVMNXA	Service Order#	5395966	
Work Activity	Fiber-Buried	Capital	N	Maintenance	Y
Customer Name	CHRIS TAYLOR		Phone#	(763) 416-3849	
Address	6659 INLAND LN N		One Call Ticket#		
City & Zip	MAPLE GROVE 55311				
Location/Directions					
Description of Work or Special Instructions	BURY ONU TO NID. HARDENED END IN NID				

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	6123844803
Tech Name and Tech #	DEX KOEPP		Employee Contact#	6513025304			
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments			
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	SEPCUTOVER	CUTOVER BSW	1				
Parish/County	BM83	BSW guard at house					
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used			
Township:	BM61(1.25)SEB	BSW Bore footage	100				
Section	SEBO PER FT LBR	Fiber & plow plcmt					
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	165				
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit			
	Permit	Permit	1	Any placement within the ROW requires a permit			
Nearest cross st.			Plat Page	Map#			



Originated By: **DEX KOEPP** Date: **8/8/22** Completed By: _____ Date: _____
 Authorized By: (SRO) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (MRO) _____ Date: _____
 Email sketch to: _____

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	