


Revised 05-27-2021	State	MN	Contractor	MN Metro	CMS#	22121193
CenturyLink BSW Order/Maintenance Work Authorization						
Company	Exchange Name	OSSEMNXO			Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N	
Customer Name	ryne reuvers	Phone#	(150) 002-4931			
Address	18582 69th pl n			One Call Ticket#		
City & Zip	Mpale Grove, MN					
Location/Directions	SEE SKETCH FOR DETAILS					
Description of Work or Special Instructions	SEE SKETCH FOR DETAILS					

Held Order	Y	N	Permit:	Y	N	Bore:	Y	N	CBR#	612 845 8254
Tech Name and Tech #	AA10109				Employee Contact#	7632288645				
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments					
	Description	Notes								
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt								
	SEB3-22T	BSW-3 & hand dig plcmt								
Ped#	SEE SKETCH	SEPCUTOVER	CUTOVER BSW	1						
Parish/County	BM83	BSW guard at house		1						
	XXSEB-GL	Remove temp drop		400	Footage when temp can't be re-used					
Township:	NA	BM61(1.25)SEB	BSW Bore footage	55						
Section	NA	SEBO PER FT LBR	Fiber & plow plcmt	130						
Range	NA	SEBO PER FT LBR T	Fiber & hand dig plcmt							
	SEB6-22	BSW-6 & plow plcmt								
	BM2(5/8)(8)	Ground Rod								
	SEBO-COIL	Fiber Coil		1	Coil excess on Fiber drop add 1 unit					
	Permit	Permit		1	Any placement within the ROW requires a permit					
Nearest cross st.	SEE SKETCH			Plat Page	Map#					



Originated By:	AA10109	Date:	8/12/22	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker