

| | | | | | | |
|-----------------------|-------|----|------------|----------|------|----------|
| Revised 05-27-2021 | State | MN | Contractor | MN Metro | CMS# | 22112921 |
|-----------------------|-------|----|------------|----------|------|----------|

CenturyLink BSW Order/Maintenance Work Authorization

| | | | | | |
|---|------------------|------------------|----------------|-------------|---|
| Company | Exchange Name | HAML MN HB | Service Order# | 466987 | |
| Work Activity | Fiber-Aerial | Capital | N | Maintenance | Y |
| Customer Name | dinesh goel | Phone# | (763) 476-5936 | | |
| Address | 19043 64th ave n | One Call Ticket# | | | |
| City & Zip | Maple Grove | | | | |
| Location/Directions | | | | | |
| Description of Work or Special Instructions | | | | | |

| | | | | | | | |
|----------------------|----------|---------|-------------------|------------|---|------|------------|
| Held Order | N | Permit: | y | Bore: | y | CBR# | 7635484632 |
| Tech Name and Tech # | rico 838 | | Employee Contact# | 6128163956 | | | |

| Sketch (Include Cntr Line & Pedestal) | Material/Labor Units | | Footage/Quantity | Comments |
|--|----------------------|------------------------|------------------|--|
| | Description | Notes | | |
| Cntr Line foot | SEB3-22 | BSW-3 & plow plcmt | | |
| | SEB3-22T | BSW-3 & hand dig plcmt | | |
| Ped# | SEPCUTOVER | CUTOVER BSW | 1 | |
| Parish/County | BM83 | BSW guard at house | | |
| Township: | XXSEB-GL | Remove temp drop | | Footage when temp can't be re-used |
| Section | BM61(1.25)SEB | BSW Bore footage | 63 | |
| Range | SEBO PER FT LBR | Fiber & plow plcmt | | |
| | SEBO PER FT LBR T | Fiber & hand dig plcmt | 40 | |
| | SEB6-22 | BSW-6 & plow plcmt | | |
| | BM2(5/8)(8) | Ground Rod | | |
| | SEBO-COIL | Fiber Coil | | Coil excess on Fiber drop add 1 unit |
| | Permit | Permit | | Any placement within the ROW requires a permit |

| | | | | | |
|-------------------|--|-----------|--|------|--|
| Nearest cross st. | | Plat Page | | Map# | |
|-------------------|--|-----------|--|------|--|



| | | | | | | | |
|----------------------|----------|-------|---------|---------------|--|-------|--|
| Originated By: | Rico 838 | Date: | 7/29/22 | Completed By: | | Date: | |
| Authorized By: (SRO) | | Date: | | Inspected By: | | Date: | |
| Authorized By: (MRO) | | Date: | | | | | |

| | | | |
|---|--|---|--|
| 1. Distance of the bury in Right-of-Way | | 3. Distance to the nearest intersection | |
| 2. Distance from the terminal to the centerline | | 4. Nearest State Hwy mile marker | |