


Revised 05-27-2021	State MN	Contractor MN Metro	CMS#	22139863-HELD
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name OSSEMNXO	Service Order# SA-1011723		
Work Activity Fiber-Buried	Capital Y	Maintenance N		
Customer Name RICHARD BROWN	Address 9776 101ST PL N	Phone# (150) 004-2180		
City & Zip MAPLE GROVE 55369	One Call Ticket#			
Location/Directions				
Description of Work or Special Instructions QF. BURY PED TO NID. HARDENED END IN NID				
Held Order	Y	Permit: Y	Bore: Y	CBR# 7633440347
Tech Name and Tech # DEX KOEPP	Employee Contact# 6513025304			
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	90	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	160	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.			Plat Page	Map#



Originated By: DEX KOEPP	Date: 9/13/22	Completed By:	Date:
Authorized By: (SRO)	Date:	Inspected By:	Date:
Authorized By: (MRO)	Date:		

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker