


**CenturyLink BSW Order/Maintenance Work Authorization**

Company	Exchange Name	MPGVMNXA	Service Order#
Work Activity	Fiber-Buried	Capital	Y
Customer Name	VenkataSatyanarayanaMurty Mogalapalli	Phone#	
Address	11251 82nd pl n.	One Call Ticket#	
City & Zip	maple grove		
Location/Directions	pp		
Description of Work or Special Instructions	place 100ft of fiber drop with 65ft of boring driveway.		

Held Order	Y	N	Permit:	Y	N	Bore:	Y	N	CBR#	7323254079
Tech Name and Tech #	nathe				Employee Contact#	6127159213				

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped# 65	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	65	
Section	SEBO PER FT LBR	Fiber & plow plcmt	100	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	Balsam La N.		Plat Page	Map#



Originated By:	nathe	Date:	9/21/22	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way	0	3. Distance to the nearest intersection	0
2. Distance from the terminal to the centerline	0	4. Nearest State Hwy mile marker	0