


Revised 05-27-2021	State MN	Contractor MN Metro	CMS#	22154817
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>				
Company	Exchange Name OSSEMNXO	Service Order#		
Work Activity	Fiber-Buried	Capital	Y	Maintenance N
Customer Name	MISC TICKET	Phone#		76-3425
Address	9681 102nd PI N	One Call Ticket#		
City & Zip	Maple Grove, MN 55369			
Location/Directions	SEE SKETCH FOR DETAILS			
Description of Work or Special Instructions	SEE SKETCH FOR DETAILS			

Held Order	N	Permit:	Y	Bore:	Y	CBR#	NA
Tech Name and Tech #	AA10109	Employee Contact#		7632288645			
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments			
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	SEE SKETCH	SEPCUTOVER	1				
Parish/County	BM83	BSW guard at house	1				
	XXSEB-GL	Remove temp drop	300	Footage when temp can't be re-used			
Township:	NA	BM61(1.25)SEB	90	BSW Bore footage			
Section	NA	SEBO PER FT LBR	189	Fiber & plow plcmt			
Range	NA	SEBO PER FT LBR T		Fiber & hand dig plcmt			
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit			
	Permit	Permit	1	Any placement within the ROW requires a permit			
Nearest cross st.	SEE SKETCH	Plat Page		Map#			



Originated By:	AA10109	Date:		Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					
Email sketch to:							
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			