



Local  
CMS#

CMS#

17022656 Permit

**CenturyLink Constant Job Order/Maintenance Work Authorization**

Company T866 Exchange 579 Osseo Service Order# 1421602682  
 Work Activity Drop-Buried Copper Capital x Maintenance \_\_\_\_\_  
 Customer Name Steve Scherer Phone# 763-315-1429  
 Address 8273 ARROWWOOD LN N One Call Ticket# \_\_\_\_\_  
 Location/Directions Maple Grove, MN  
 Description of Work or Special Instructions Plow 150 ft from Ped to Nid

DOR/TOG Yes \_\_\_ No x Permit: Yes \_\_\_ No x Bore: Yes x No \_\_\_ CBR# \_\_\_\_\_  
 Employee Name \_\_\_\_\_ Employee Contact# 612-4303133


Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. \_\_\_\_\_ Plat Page \_\_\_\_\_ Map# \_\_\_\_\_

Damaged facility # 8273 ONT

**SKETCH**

Tax Code \_\_\_\_\_



Originated By: <u>Evans</u>	Date: <u>1/17/17</u>	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____	_____	_____
Inspection notes: _____	_____		