


Revised 05-27-2021	State MN	Contractor MN Metro	CMS#	22170838-HELD
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name OSSEMNXO	Service Order#		20018362
Work Activity	Fiber-Buried	Capital	Y	Maintenance
Customer Name	NEPOLEON AMANCIO		Phone#	
Address	12025 84TH AVE N		One Call Ticket#	
City & Zip	MAPLE GROVE, MN			
Location/Directions				
Description of Work or Special Instructions				

Held Order	N	Permit:	N	Bore:	N	CBR#
Tech Name and Tech #	Mamadee Keita - AD22553			Employee Contact#	404-317-5848	
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments	
	Description	Notes				
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt				
	SEB3-22T	BSW-3 & hand dig plcmt				
Ped#	SEPCUTOVER	CUTOVER BSW		1		
Parish/County	BM83	BSW guard at house		1		
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used	
Township:	BM61(1.25)SEB	BSW Bore footage				
Section	SEBO PER FT LBR	Fiber & plow plcmt		180		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt				
	SEB6-22	BSW-6 & plow plcmt				
	BM2(5/8)(8)	Ground Rod				
	SEBO-COIL	Fiber Coil		1	Coil excess on Fiber drop add 1 unit	
	Permit	Permit		1	Any placement within the ROW requires a permit	
Nearest cross st.				Plat Page	Map#	



Originated By:	MAMADEE KEITA	Date:	11/8/22	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					
Email sketch to:							

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	