


CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	MPGVMNXA	Service Order#	
Work Activity	Fiber-Buried	Capital	Maintenance	Y
Customer Name	seth lindberg		Phone#	(150) 008-4737
Address	10620 103rd ave n		One Call Ticket#	
City & Zip	maple grove 55369			
Location/Directions	drop was placed on july 12th and was cut some time between now and then don't know who cut it.			
Description of Work or Special Instructions	bore neighboring yard 90 feet and hand dig to the back of house were the nid is 175 feet go around deck customer will wait till spring to get ordre done.			

Held Order	y	Permit:	y	Bore:	y	CBR#	7635871131
Tech Name and Tech #	cory cook		Employee Contact#	7632287153			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	fiber	SEPCUTOVER		
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	90	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	175	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit
	Permit	Permit		Any placement within the ROW requires a permit

Nearest cross st.	vally forge	Plat Page		Map#	
-------------------	-------------	-----------	--	------	--



Originated By:	cory cook	Date:	1/10/23	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	