


CenturyLink BSW Order/Maintenance Work Authorization

| | | | | | |
|---|---------------------|----------|------------------|-------------|---|
| Company | Exchange Name | OSSEMNXO | Service Order# | 1500094263 | |
| Work Activity | Fiber-Buried | Capital | Y | Maintenance | N |
| Customer Name | KATE ANDERSON | | Phone# | | |
| Address | 8133 EVERGREEN LN N | | One Call Ticket# | | |
| City & Zip | MAPLE GROVE, MN | | | | |
| Location/Directions | | | | | |
| Description of Work or Special Instructions | | | | | |

| | | | | | | | |
|----------------------|-------------------------|---------|---|-------------------|--------------|------|--|
| Held Order | Y | Permit: | Y | Bore: | Y | CBR# | |
| Tech Name and Tech # | Mamadee Keita - AD22553 | | | Employee Contact# | 404-317-5848 | | |

| Sketch (Include Cntr Line & Pedestal) | Material/Labor Units | | Footage/Quantity | Comments |
|--|----------------------|------------------------|------------------|--|
| | Description | Notes | | |
| Cntr Line foot | SEB3-22 | BSW-3 & plow plcmt | | |
| | SEB3-22T | BSW-3 & hand dig plcmt | | |
| Ped# | SEPCUTOVER | CUTOVER BSW | 1 | |
| Parish/County | BM83 | BSW guard at house | 1 | |
| | XXSEB-GL | Remove temp drop | | Footage when temp can't be re-used |
| Township: | BM61(1.25)SEB | BSW Bore footage | | |
| Section | SEBO PER FT LBR | Fiber & plow plcmt | 159 | |
| Range | SEBO PER FT LBR T | Fiber & hand dig plcmt | | |
| | SEB6-22 | BSW-6 & plow plcmt | | |
| | BM2(5/8)(8) | Ground Rod | | |
| | SEBO-COIL | Fiber Coil | 1 | Coil excess on Fiber drop add 1 unit |
| | Permit | Permit | 1 | Any placement within the ROW requires a permit |

| | | | | | |
|-------------------|--|-----------|--|------|--|
| Nearest cross st. | | Plat Page | | Map# | |
|-------------------|--|-----------|--|------|--|



| | | | | | | | |
|----------------------|---------------|-------|--------|---------------|--|-------|--|
| Originated By: | MAMADEE KEITA | Date: | 2/6/23 | Completed By: | | Date: | |
| Authorized By: (SRO) | | Date: | | Inspected By: | | Date: | |
| Authorized By: (MRO) | | Date: | | | | | |

| | | | |
|---|--|---|--|
| 1. Distance of the bury in Right-of-Way | | 3. Distance to the nearest intersection | |
| 2. Distance from the terminal to the centerline | | 4. Nearest State Hwy mile marker | |