

Revised 05-27-2021	State	MN	Contractor	MN Metro	CMS#	23030543-HELD
CenturyLink BSW Order/Maintenance Work Authorization						
Company	Exchange Name	MPGVMNXA			Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N	
Customer Name	Paulo Lomazzi			Phone#	150 010 7617	
Address	8066 Balsam LN N			One Call Ticket#		
City & Zip	Maple Grove, MN 55369					
Location/Directions	xxxxx					
Description of Work or Special Instructions	Total fiber placement is 67'. Total includes a 29' bore. Cut over when done.					

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	312 478 6752
Tech Name and Tech #	Nation			Employee Contact#	6515290847		
Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units			Footage/Quantity	Comments		
	Description	Notes					
Cntr Line foot#	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	xxxxx	SEPCUTOVER	CUTOVER BSW	1			
Parish/County		BM83	BSW guard at house	1			
		XXSEB-GL	Remove temp drop		Footage when temp can't be re-used		
Township:		BM61(1.25)SEB	BSW Bore footage	29			
Section		SEBO PER FT LBR	Fiber & plow plcmt	67			
Range		SEBO PER FT LBR T	Fiber & hand dig plcmt				
		SEB6-22	BSW-6 & plow plcmt				
		BM2(5/8)(8)	Ground Rod				
		SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit		
		Permit	Permit	1	Any placement within the ROW requires a permit		
Nearest cross st.	81st Ave N			Plat Page		Map#	



Originated By:	Jonas Nation	Date:	3/9/23	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way	0	3. Distance to the nearest intersection	0
2. Distance from the terminal to the centerline	0	4. Nearest State Hwy mile marker	0