


CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name ANOKMNAN	Service Order# A00245756
Work Activity Fiber-Buried	Capital Y	Maintenance
Customer Name Ari Skalisk7	Phone# 218 590 4270	One Call Ticket#
Address 11471 81st PI N	City & Zip Maple Grove Mn 55369	
Location/Directions		
Description of Work or Special Instructions		

Held Order	N	Permit: Y	Bore:	N	CBR# 150 011 0496
Tech Name and Tech # Sanchez Moore 953	Employee Contact# 651 387 9385				

Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage		
Section	SEBO PER FT LBR	Fiber & plow plcmt	102	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.			Plat Page	Map#



Originated By:		Date:		Completed By:	_____	Date:	_____
Authorized By: (SRO)		Date:	_____	Inspected By:	_____	Date:	_____
Authorized By: (MRO)		Date:	_____		_____		_____

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker	