

Revised 05-27-2021	State MN	Contractor MN Metro	CMS#	23053624-HELD
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>				
Company	Exchange Name MPGVMNXA	Service Order#	21373272	
Work Activity	Fiber-Buried	Capital	Y	Maintenance N
Customer Name	hoa building	Phone#	(150) 010-7591	
Address	18403 75th pl n	One Call Ticket#		
City & Zip	maple grove 55311			
Location/Directions				
Description of Work or Special Instructions	order shows old address 7549 urbandale ln n. new is the one list one order.			

Held Order	y	Permit:	y	Bore:	y	CBR#	na
Tech Name and Tech #	Rico AB20004			Employee Contact#	6128163956		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments		
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	SEPCUTOVER	CUTOVER BSW		1			
Parish/County	BM83	BSW guard at house		1			
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used		
Township:	BM61(1.25)SEB	BSW Bore footage		112			
Section	SEBO PER FT LBR	Fiber & plow plcmt					
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		30			
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	SEBO-COIL	Fiber Coil		1	Coil excess on Fiber drop add 1 unit		
	Permit	Permit		1	Any placement within the ROW requires a permit		
Nearest cross st.		Plat Page		Map#			



Originated By:	Rico 838	Date:	4/25/23	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	