

Revised 05-27-2021	State	MN	Contractor	MN Metro	CMS#	23123600
-----------------------	-------	----	------------	----------	------	----------


CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	ANOKMNAN	Service Order#	A00352746
Work Activity	Fiber-Buried	Capital	Maintenance	
Customer Name	Janell Jaeger	Phone#		
Address	7188 Walnut Grove Ln N	One Call Ticket#		
City & Zip	Maple Grove Mn 55312			
Location/Directions				
Description of Work or Special Instructions				

Held Order	Y	Permit:	Y	N	Bore:	Y	CBR#	1500187184
Tech Name and Tech #	Sanchez Moore 953			Employee Contact#	6513879385			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	50	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	62	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil		Coil excess on Fiber drop add 1 unit
	Permit	Permit		Any placement within the ROW requires a permit

Nearest cross st.		Plat Page		Map#	
-------------------	--	-----------	--	------	--



62 ft

Originated By:		Date:		Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:		1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
		2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker