

16105859 PERMIT


CenturyLink BSW Order/Maintenance Work Authorization

Company	T600	Exchange#	Fernbrook W/C	Service Order#	MN VN293544
Work Activity	BSW Bury to PR			Capital	<input checked="" type="checkbox"/>
Customer Name	Brenda Anderson			Maintenance	<input type="checkbox"/>
Address	6809 Quantico Ln N			Phone#	763 557 0831
City & Zip	Maple Grove MN 55311			One Call Ticket#	
Location/Directions	Boss Lake Rd west - South on Quantico Ln N.				

763 559 6312

Hold Order?	No	Permit:	<input checked="" type="checkbox"/>	Bore:	<input checked="" type="checkbox"/>	CBR#	763 557 0831
Employee Name	230			Employee Contact#	612 272 9955		

(include Cntr Line & Pedestal)	Material/Labor Units		Est Qty	Actual Qty	Placed by (Foreman/Crew Name)
	Description	Notes			
Cntr Line fod	SEB3-22	Place 3 pair BSW		120'	
Ped#	SEPCUTOVER	CUTOVER BSW	1		
County	BM83	BSW guard at house			
Township:	Henn	XXSEB-GL	Remove temp drop	200	
Section		BM61(1.5)D	BSW Bore required	20'	
Range		SEB3-22T	Hand Dig		
Nearest cross st.		SEBOP2	Fiber Drop		
Damaged facility #		68th Ave N + Quantico Ln N	Plat Page		Map#



Originated By:	<i>[Signature]</i>	Date:	5/18/16	Completed By:		Date:	
Authorized By: (APS)	James	Date:	5/16	Inspected By:		Date:	
Authorized By: (AOM)		Date:				Date:	

Inspection Notes:	MetroBSW@centurylink.com		
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline:		4. Nearest State Hwy mile marker	