


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order#
 Work Activity Drop-Buried Copper FIBER Capital X Maintenance
 Customer Name JARED SKINNER Phone# 763-315-5414
 Address 16961 76th Ave NE One Call Ticket#
 Location/Directions Maple Grove
 Description of Work or Special Instructions

DOR/TOG Yes ___ No x Permit: Yes ___ No x Bore: Yes x No x CBR# 612-499-1044
 Employee Name Joe Vukelich Employee Contact# joe.vukelich

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty	Actual Qty	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
 SKETCH



JOE VUKELICH	Date: 5/23/10	Completed By:	Date:
	Date:	Inspected By:	Date:
	Date:		