


X	Local Exch#	Fernbrook WC	CMS#	
CenturyLink BSW Order/Maintenance Work Authorization				
Company	T600	Exchange	763 553	Service Order# N58002354
Work Activity		Capital	X	Maintenance
Customer Name	Archie's Lock & Safe			Phone# 763-559-7842
Address	6233 N. Annapolis Ln			One Call Ticket#
City & Zip	Maple Grove 55311			
Location/Directions				
Description of Work or Special Instructi				
Held Order ?	N	Permitt	(N) No Bore (Y)	NC CBR# 952-292-7786
Employee Name	Jason Archuleta			Employee Contact# 612-270-9612
Sketch	Material/Labor Units		Est	Actual
(Include Cntr Line & Pedestal)	Description	Notes	Qty.	Qty
Cntr Line fod	SEB3-22	Place 3 pair BSW	100	
Ped#	SEPCUTOVER	CUTOVER BSW	1	
County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop	120	
Township:	BM61(1.5)D	BSW Bore required	15	
Section	SEB3-22T	Hand Dig		
Range	SEBOP2	Fiber Drop		
Nearest cross st.	Annapolis & 62nd Ave N.		Plat Page	Map#
Damaged facility #				



Originated By: Jason Archuleta	Date: 12-22-16	Completed By:	Date:
Authorized By: (APS) James	Date: 12-27-16	Inspected By:	Date:
Authorized By: (AOM)	Date:		
Inspection Notes: MetroBSW@centurylink.com			
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline:		4. Nearest State Hwy mile marker	