


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity **Drop-Buried Copper FIBER** Capital Maintenance
 Customer Name Tom Stoll Phone# 763-416-1622
 Address 16910 66th Pl N One Call Ticket# _____
 Location/Directions Maple Grove
 Description of Work or Special Instructions _____

DOR/TOG Yes ___ No Permit: Yes ___ No Bore: Yes No CBR# 612-499-1044
 Employee Name Joe Vukelich Employee Contact# joe.vukelich

Sketch (Include Line & Pedestal)	Material/Labor Units		Est	Actual	Placed by (Foreman/Crew Name)
	Description	Notes	Qty.	Qty.	
Line					
Ped#					
Parish/County					
Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
 SKETCH _____



Originated By: JOE VUKELICH Date: 5/11/10 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____