


Local CMS#

CMS#

Century Link Constant Job Order/Maintenance Work	

CenturyLink Constant Job Order/Maintenance Work Authorization											
Company	T866	Exchange	579 Os	seo					Service Order#		17021013
Work Activity	Drop-Bu	uried Copper				C	apital	Х	Mainter	nance	
Customer Name	Thomas	Branch				•			Phone#	763-	315-3875
Address	10213 U	10213 UNION TERRACE LN N						One	Call Ticket#		
Location/Directions	Maple G	rove, mn					_		•		
Description of Work or	Special Insti	ructions	Plow 22	25' from MST	to hous	e w/ 2	30' bore	es.			
DOR/TOG	Yes	No x Permit	· Vas	No x Bo	ra. Vas	Х	No		CBR# 484-46	7-5552	
Employee Name	Kris Tow		. 103	_ NO _ X _ DOI	ic. 163		yee Co	ntact#			
Sketch		Material/Labor Units				Est	Actual	Placed by			
(Include Line & Pedestal)		Description		Notes		Qty.	Qty	(Foreman/Crew Name)			
Line											
Ped#											
Parish/County											
Hennipen											
Township:											
Section											
Range											
GPS Reading											
Negroot groot of						Dlat	Dono		Mon#		
Nearest cross st.						Plat	Page		Map#		– .
Damaged facility # SKETCH			_						Tax Code		-N -



Originated By:	Townsend	Date:	1/25/17	Completed By:	Date:
Authorized By: (APS)		Date:		Inspected By:	Date:
Authorized By: (AOM)		Date:		_	
Inspection notes:				_	