


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order#  
 Work Activity Drop-Buried Copper Capital X Maintenance   
 Customer Name GINA McDonald Phone# 763-424-2890  
 Address 11842 84th TERR. N One Call Ticket#  
 Location/Directions Maple Grove, MN  
 Description of Work or Special Instructions

DOR/TOG Yes \_\_\_ No  Permit: Yes \_\_\_ No  Bore: Yes  No  CBR# 612-499-1044  
 Employee Name Joe Vukelich Employee Contact# joe.vukelich

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. \_\_\_\_\_ Plat Page \_\_\_\_\_ Map# \_\_\_\_\_  
 Damaged facility # \_\_\_\_\_



Originated By: JOE VUKELICH Date: 6/1/16 Completed By: \_\_\_\_\_ Date: \_\_\_\_\_  
 Authorized By: (APS) \_\_\_\_\_ Date: \_\_\_\_\_ Inspected By: \_\_\_\_\_ Date: \_\_\_\_\_  
 Authorized By: (AOM) \_\_\_\_\_ Date: \_\_\_\_\_  
 Inspection notes: \_\_\_\_\_