

CenturyLink Constant Job Order/Maintenance Work Authorization


Company T866 Exchange 579 Osseo Service Order#
 Work Activity Drop-Buried Copper *21 Bar* Capital X Maintenance *3*
 Customer Name SCOTT CARLSON Phone# 763-405-6859
 Address 10705 Quaker Ln N One Call Ticket#
 Location/Directions Maple Grove
 Description of Work or Special Instructions

DOR/TOG Yes No Permit: Yes No Bore: Yes No CBR# 612-499-1044
 Employee Name Joe Vukelich Employee Contact# joe.vukelich

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty	Actual Qty	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County					
Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____

SKETCH



Originated By: JOE VUKELICH Date: 5/31/16 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____