

CenturyLink Constant Job Order/Maintenance Work


16120837 HELD ORDER PERMIT

Company T866 Exchange 579 Osseo Service Order#
 Work Activity Drop-Buried Copper Fiber Capital X Maintenance *
 Customer Name NICK SCHEIFER Phone# 763-315-4313
 Address 11921 85th A N. One Call Ticket#
 Location/Directions Maple Grove
 Description of Work or Special Instructions

DOR/TOG Yes ___ No Permit: Yes ___ No Bore: Yes No CBR# 612-499-1044
 Employee Name Joe Vukelich Employee Contact# joe.vukelich

Sketch (Include Line & Pedestal)	Material/Labor Units		Est	Actual	Placed by (Foreman/Crew Name)
	Description	Notes	Qty.	Qty	
Line					
Ped#					
Parish/County Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____



Originated By: JOE VUKELICH Date: 6/3/16 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____