

CenturyLink Constant Job Order/Maintenance W


Company T866 Exchange 579 Osseo Service Order#
 Work Activity Drop-Buried Copper FIBER Capital X Maintenance *
 Customer Name MARK CHURP Phone# 763-424-1825
 Address 10798 ZOPFI WAY E One Call Ticket#
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions

DOR/TOG Yes No x Permit: Yes No x Bore: Yes X No * CBR# 612-499-1044
 Employee Name Joe Vukelich Employee Contact# joe.vukelich

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____
 SKETCH

Tax Code _____



Originated By: JOE VUKELICH Date: 6/14/16 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____