

CenturyLink Constant Job Order/Maintenance Work Authorization


Company T866 Exchange 579 Osseo Service Order#  
 Work Activity Drop-Buried Copper Maintenance x  
 Customer Name Capital x  
 Address 8513 OAKVIEW Way Phone#  
 Location/Directions Maple Grove, MN One Call Ticket#  
 Description of Work or Special Instructions

DOR/TOG Yes No x Permit: Yes No x Bore: Yes x No \* CBR# 612-499-1044  
 Employee Name Joe Vukelich Employee Contact# joe.vukelich

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County					
Henripen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. \_\_\_\_\_ Plat Page \_\_\_\_\_ Map# \_\_\_\_\_  
 Damaged facility # \_\_\_\_\_

SKETCH Tax Code \_\_\_\_\_



NEW FIBER DROP TO 8513 is to Replace Existing FIBER that was CUT

Originated By: JOE VUKELICH Date: 6/2/16 Completed By: \_\_\_\_\_ Date: \_\_\_\_\_  
 Authorized By: (APS) \_\_\_\_\_ Date: \_\_\_\_\_ Inspected By: \_\_\_\_\_ Date: \_\_\_\_\_  
 Authorized By: (AOM) \_\_\_\_\_ Date: \_\_\_\_\_  
 Inspection notes: \_\_\_\_\_