



Local
CMS#

16128520 HELD ORDER PERMIT

CenturyLink Constant Job Order/Maintenance Work Authorization


Company: T866 Exchange: 579 Osseo Service Order# _____
 Work Activity: Drop-Buried Copper Fiber Capital: X Maintenance: *
 Customer Name: J. David Durham Phone#: 763-425-1227
 Address: 9992 107th Pl N One Call Ticket# _____
 Location/Directions: Maple Grove
 Description of Work or Special Instructions: _____

DOR/TOG: Yes ___ No x Permit: Yes x No * Bore: Yes x No * CBR#: 612-499-1044
 Employee Name: Joe Vukelich Employee Contact#: joe.vukelich

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty	Actual Qty	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County					
Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
 SKETCH

Fiber Drop



NEW CMS - 4-9992 107th Pl. N
 Maple Grove, MN

Originated By: JOE VUKELICH	Date: <u>still</u>	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____	_____	Date: _____
Inspection notes: _____	_____		