

CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order#
 Work Activity Drop-Buried Copper FIBER Capital X Maintenance ~~X~~
 Customer Name J. DAVID DURHAM Phone# 763-425-1727
 Address 9992 107th Pl N One Call Ticket#
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions


DOR/IOG Yes ___ No x Permit: Yes ___ No x Bore: Yes Y No ~~X~~ CBR# 612-499-1044
 Employee Name Joe Vukelich Employee Contact# joe.vukelich

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty	Actual Qty	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County Hennepin					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____
 SKETCH _____

FIBER Drop - 210'
 Road Push - 55'
 Dw Push - 25'

Tax Code



Revised 6/29/16

Originated By: JOE VUKELICH Date: 6/29/16 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____